



Technical Information Bulletin

Date 5/9/2005

Model: HD8370 S/N: T1130-T1149

Symptom:

The book stop label may have been incorrectly positioned on the knob. The 9/16" position may actually position the book stops to the back of the machine and the 1/4" position places the book stops forward on the machine.

Solution:

Contact Performance Design Inc. for a new book stop decal.

Instructions:

Apply new decal so that the 1/4" position of the new decal is overlaid onto the 9/16" mark of the original decal.



Performance Design 2350 E. Braniff St. Boise, ID. 83716
Phone: 1-800-390-5782 Fax: 1-800-390-5783
Hours: 8:00 AM-5:00 PM Mountain Standard Time